



# VGN MARBLE ARCH – PROJECT PROGRESS UPDATE AS OF 14-11-2025



**DINING**





**KITCHEN**



# LIVING ROOM





# BEDROOM





14-11-2025

**A-BLOCK – ARCH WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – FRONT SIDE ELEVATION: SECOND COAT  
PAINTING WORK HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – SECOND COAT EXTERIOR PAINTING WORK  
ON THE NORTH FACING SIDE HAS BEEN COMPLETED**





**A-BLOCK – ENTRANCE GLASS WORK HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – STILT FLOOR MARBLE WORK  
HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – STAIRCASE HANDRAIL WORK  
HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – FIRST FLOOR CORRIDOR SECOND COAT  
PAINTING WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – FIRST, SECOND AND THIRD FLOOR DOOR  
INSTALLATION WORK HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – FIRST FLOOR SECOND COAT PAINTING  
WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK FIRST FLOOR – SECOND COAT PAINTING  
WORK HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – FIRST FLOOR KITCHEN COUNTERTOP  
WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – FIRST FLOOR BATHROOM SHOWER GLASS  
FIXING WORK HAS BEEN COMPLETED**



**A-BLOCK – FIRST FLOOR BATHROOM CP FITTING  
WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – SECOND FLOOR CORRIDOR SECOND COAT PAINTING WORK HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – CORRIDOR CEILING LIGHTING WORK  
HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – STAIRCASE LIGHTING WORK HAS  
BEEN COMPLETED**



14-11-2025

**A-BLOCK – SECOND FLOOR BATHROOM CP  
FITTING WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – THIRD FLOOR SECOND COAT PAINTING  
WORK IN THE CORRIDOR HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – THIRD FLOOR SECOND COAT  
PAINTING WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – THIRD FLOOR SECOND COAT  
PAINTING WORK HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – THIRD FLOOR KITCHEN COUNTERTOP  
WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – THIRD FLOOR BATHROOM CP  
FITTING WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – FIRST, SECOND AND THIRD FLOOR BALCONY  
HANDRAIL WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – SOLAR PANEL INSTALLATION WORK  
HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – EXTERNAL ELEVATION LIGHTING  
WORK HAS BEEN COMPLETED**





**A-BLOCK – EXTERNAL ELEVATION CCTV  
CAMERA FIXING WORK HAS BEEN COMPLETED**



14-11-2025

**A-BLOCK – LIFT WORK HAS BEEN COMPLETED**





14-11-2025

**A-BLOCK – PAVER BLOCK ROAD WORK HAS  
BEEN COMPLETED**





14-11-2025

**A-BLOCK – CAR PARKING EV CHARGING POINT  
WORK HAS BEEN COMPLETED**





**A-BLOCK – BOOM BARRIER WORK HAS BEEN  
COMPLETED**



14-11-2025

**B-BLOCK – SECOND COAT PAINTING WORK ON  
THE FRONT ELEVATION HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – SECOND COAT PAINTING WORK ON  
THE STILT FLOOR HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK – SECOND COAT PAINTING WORK ON  
THE STILT FLOOR HAS BEEN COMPLETED**



1		Marble Arch	B- BLOCK
B101		MR. RICHARD & MRS. ALISHA	
B102		MRS. SHARMILA DEVI M	
B103		MRS. BHAVYA CHANDRAMOULI	
B104		MR. AYYAKKUTTI V	
2			
B201		MS. PADMAPRIYA K	
B202		MS. GAYATHRI GUNALAN	
B203			
B204		MR. SANDEEP VENKATACHARI	
B301		MR. RAJESH P	



14-11-2025

**B-BLOCK – ENTRANCE GLASS WORK HAS  
BEEN COMPLETED**



14-11-2025

**B-BLOCK – STAIRCASE HANDRAIL WORK  
HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – MARBLE WORK HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK – LIFT WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – 1<sup>ST</sup> , 2<sup>ND</sup> & 3<sup>RD</sup> FLOOR CORRIDOR SECOND COAT PAINTING WORK HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK FIRST AND SECOND FLOOR – DOOR  
INSTALLATION WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – FIRST FLOOR SECOND COAT  
PAINTING WORK HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK – FIRST FLOOR SECOND COAT  
PAINTING WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – WINDOW FRAME AND DOOR FIXING WORK ON  
THE FIRST AND SECOND FLOOR HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK – FIRST FLOOR KITCHEN COUNTERTOP  
WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – FIRST FLOOR TOILET FALSE CEILING  
WORK HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK – FIRST FLOOR SHOWER GLASS  
PARTITION WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – SECOND FLOOR FIRST COAT  
PAINTING WORK HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK – SECOND FLOOR KITCHEN  
COUNTERTOP WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – SECOND FLOOR TOILET FALSE  
CEILING WORK HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK – SECOND FLOOR SHOWER GLASS  
PARTITION WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – FIRST, SECOND AND THIRD FLOOR WINDOW  
FIXING WORK HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK – DOOR INSTALLATION WORK ON THE  
THIRD FLOOR HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – THIRD FLOOR PAINTING WORK HAS  
BEEN COMPLETED**



14-11-2025

**B-BLOCK – THIRD FLOOR PAINTING WORK  
HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – THIRD FLOOR TOILET FALSE CEILING  
WORK HAS BEEN COMPLETED**



14-11-2025

**B-BLOCK – THIRD FLOOR SHOWER GLASS  
PARTITION WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – TERRACE COOLING TILE WORK  
HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – TERRACE SOLAR PANEL  
INSTALLATION WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – EXTERNAL ELEVATION LIGHT  
FIXING WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – EXTERNAL ELEVATION CCTV CAMERA  
FIXING WORK HAS BEEN COMPLETED**





14-11-2025

**B-BLOCK – PAVER BLOCK ROAD WORK HAS  
BEEN COMPLETED**



**B-BLOCK – BOOM BARRIER WORK HAS BEEN COMPLETED**





14-11-2025

**A & B-BLOCK – D.G WORK HAS BEEN COMPLETED**





14-11-2025

**A & B-BLOCK – CENTER PAVER BLOCK ROAD  
WORK HAS BEEN COMPLETED**





**THANK YOU**